

Division of Oil, Gas, & Mining
Mining Report

07/26/93

MINE ID: S0370080

MINE NAME: LASAL MILL

OPERATOR: SAGUARRO MINING
CONTACT: LARRY HILL; ALAN LEVIN
ADDRESS: LASAL JUNCTION
LASAL JUNCTION UT 84530

PHONE: (801)686-2365

Surface Owner: FEE
Mineral Owner: FEE

BLM #:
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
						0	0.0	0.0

Permit Status: NAP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): PRO

Acreage: 0

Minerals Mined

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

/ /

/ /

/ /

07/16/93

BOND TYPE:

BOND AMOUNT:

ANNUAL REPORT YEAR:

	YTD	Total				
NONCOMP NOTICES:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /
AMENDMENTS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /

COMMENTS:

THIS IS AN UNPERMITTED SITE. THE SITE WAS PERMITTED EARLIER BY MR. PAUL SCOFIELD. MR. SCOFIELD RECLAIMED THE SITE SHORTLY AFTER INITIATING OPERATION TWO YEARS PREVIOUS (1991). NEW OWNERS HAVE TAKEN OVER THE SITE & INITIATED A NEW GOLD MILLING OPERATION. SMO WAS GIVEN TO THE NEW OPERATOR. JOHN STEVENSON IS INVOLVED IN DEVELOPING THE SITE. INSPECTION MADE 5/93 AND AGAIN 7/93. STILL NOT PERMITTED TO DATE. ALAN LEVIN IS CO-OWNER OF THE OPERATION.